ENGINEERING CHANGE REQUEST (ECR)

ECR Number: Page 1								
ECR Title: CCG CONTROLLER REPLACEMENT								
Key S/S or Assy: S/S or Assy Name: Microwave Control Assembly								
ECR Status: **APPROVED FOR IMPLEMENTATION** Date: 03/08/2002								
Orignator: Arthur J. Freiley Badge Number: 106439								
Type: PERMANENT Priority Routine								
Add or modify interface: Yes No threat to either the successful performance of a mission,								
Task Identification: CCG UNIFICATION TASK, PHASE II or to personnel. Process in a timely manner.								
Funds Available? YES Estimated Implementation Cost: 2233K								
PROBLEM, NEED FOR CHANGE (include Impact if NOT done):								
The UWV CCG Systems were implemented over a 6 to 8 year period with various models of PCs and operating system versions that are no longer supported by the manufacturer. This makes it difficult to implement uniform changes to all controllers network wide. The current controllers are legacy systems conforming to the obsolete 890 series protocals and requirements. The subsystem controllers need to be upgraded to meet the current MON requirements.								
This implementation will be phase II of the CCG Unification Task.								
IMPACT-IF-NOT-DONE:								
The UWV controllers will continue to be a legacy system with an obsolete operating system. When the NMC discontinues support of the legacy system, the UWV subsystem will be unable to provide monitor and control functions.								

Printed On: 05/27/2003

ENGINEERING CHANGE REQUEST (ECR)

ECR Number: ECR Title:		<u>0007</u> ROLLER RE	Key S/S or PLACEMENT		110.101			Page 2	
PROPOSED SOLUTION:									
This change to	the CCG e	quipment wi	ill replace th . The new	ne PC contr controllers	oller and O	S-2 operating systems d support all MON req	with new SUN uirements.	Computers with	
Other Assembli	es affected								
Other Assemblies affected: 110.106									
AFFECTED LOCATION(s)									
GOLDSTONE:	DSS-27	DSS-26	DSS-25	DSS-24	DSS-15	DSS-14			
CANBERRA: MADRID: JPL: OTHER:	DSS-45 DSS-65 DTF-21	DSS-43 DSS-63	DSS-34 DSS-55	DSS-54					
Related ECRs:	1.	.0040							

Printed On: 05/27/2003